


**Weathered Rock Slope with  
Protruded Soil Nail Head**

COPY RIGHT ®

<p>Project: Contract No. GE/2005/39 10 Year Extended Landslip Preventive Measures Project, Phase 4, Package H Feature No. 11NW-D/C76, Junction of Shun Yung Street and Fat Kwong Street</p>	 <p><b>TOYO GREENLAND CO., LTD.</b></p>
<p>Drawing Title: Typical Detail of Installation of Eco-Bags On the Top Surface &amp; below the Bottom Surface of Protruded Soil Nail Head</p>	
<p>Check : Ho Tat Pui, Daniel</p>	<p>Scale : N.T.S.</p>
<p>Ref.: C1597/07/TGD0003 - Sketch (i)</p>	<p>Date: 22 January 2007</p>